



Technical Bulletin

Bulletin #: 020217

Issue Date: February, 2 2017

FA, MA-ST, and RTA Hot Wire Part Number

This bulletin is to inform distributors that the part number on the spare parts lists and mechanical drawings for FA, MA-ST, and RTA machines with the hot wire film tail treatment may be incorrect. For end users with these machine types with the hot wire film tail treatment, please verify that the spare parts list and mechanical drawing part number are correct and update applicable records with the correct part number. The part description affected is “**FILM TAIL CUTTING WIRE 30.**”

- Incorrect Part Number: **D0249447NO**
- Correct Part Number: **1006909NO**