



Technical Bulletin

Bulletin #: V090109-01

Issue Date: September 1,
2009

Flex Build Procedure Change - Flex Film Tail Treatment

Summary

The FLEX HPA and LPA 20" film tail treatment has been redesigned for additional adjustability. This design will allow capability to wrap a wider range of loads with a consistent film cut.

Procedure Change

Starting with serial number V938, all HPA and LPA machines will receive an improved design film tail treatment that provides consistent film cutting on a wider range of loads. The new assembly numbers for the 20" film tail treatment are:

- HPA – 264680
- LPA – 264700

The previous drawings were:

- HPA – 256567
- LPA – 256566

The re-designed 30" film tail treatment is not yet released, but will be created on a needed basis.

Instructions to Distributors

Please note the listed changes for your records and inform your sales and technical staff as to the benefits to both the distributor service network and end users.