



Technical Bulletin

Bulletin #: V091009-01

Issue Date: September 10, 2009

Flex Build Procedure Change - Flex Instacut Re-design

Summary

Instacut film delivery has been improved to reduce possible film damage. The new design removes the brush and mount from its current location on the door. The adjustable roller that was bolted on the carriage backplate was removed and a new mount was made for the brush to take its place. The new brush location is adjustable just as the roller was and the brush is bolted onto that mount so it has an additional adjustment.

Procedure Change

The 20" carriage and 30" carriages have been updated to reflect the change. Contact your distributor for more information.

Instructions to Distributors

Please note the listed changes for your records and inform your sales and technical staff as to the benefits to both the distributor service network and end users.

Previous Design



New Design

